Monitoring Data Record

Project Title: B-4183	
COE Action ID: 2011-00417 DWQ Number: 20110060	_
Stream Name: Crooked Creek and Middle Fork Creek	
City, County and other Location Information: Madison County, replaced Br. #29 over Midd	le
Fork Creek and Br. #28 over Crooked Creek on SR 1526 adjacent to US 19	
Date Construction Completed: Completed Planting on 11-26-12 Monitoring Year: (4) of 5	
Ecoregion: Broad Basins 8 digit HUC unit 06010105	
USGS Quad Name and Coordinates: 35.85350, -82.48853	
Rosgen Classification:	
Length of Project: 107' Urban or Rural: Rural Watershed Size: 7.6 sq. mi.	
Monitoring DATA collected by: M. Green & J. Young Date: 7/8/15	
Applicant Information:	
Name: NCDOT Roadside Environmental Unit	
Address: 1425 Rock Quarry Road Raleigh, NC 27610	
Telephone Number: (919) 861-3772 Email address: mlgreen@ncdot.gov	
Consultant Information:	
Name:	
Address:	
Telephone Number: Email address:	
Project Status: Complete	
Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1 2 3	
Monitoring Level 1 requires completion of Section 1, Section 2 and Section 3	
Permit States: (ACOE Permit Requirements):	
Condition #4. While the channel relocation of a portion of Crooked Creek is not designed to mimic natural patter	
profile and dimension, stability of the relocated channel is a concern. The permittee shall perform monitoring for	5

Condition #4. While the channel relocation of a portion of Crooked Creek is not designed to mimic natural pattern, profile and dimension, stability of the relocated channel is a concern. The permittee shall perform monitoring for 5 years on the relocated channel. This monitoring will include reference photos, plant survival (i.e., identify specific problem areas such as missing, stressed, damaged or dead plantings, estimate causes, and propose remedial actions), and visual inspections of channel stability; physical measurements of channel stability/morphology will not be performed. A monitoring report will be submitted to the USACE within sixty days after completion of the monitoring period. If, during the 5-year monitoring period, aggradation, degradation, bank erosion, or any other evidence of other minor instability occurs which is attributable to design of the relocated stream or work conducted by the permittee or the permittee's contractor(s), the permittee, upon discovery of the instability, shall contact the USACE and recommend corrective action; this corrective action must be approved by the USACE prior to implementation by the permittee.

Condition #5. The permittee shall monitor the stability of the right bank of Middle Fork Creek, at and immediately downstream of the confluence of Crooked Creek and Middle Fork Creek for 5 years. This monitoring will include reference photos and visual inspection of channel stability; physical measurements of channel stability/morphology will not be performed. A monitoring report will be submitted to the USACE within sixty days after completion of the monitoring period. If during the 5-year monitoring period, aggradation, degradation, bank erosion, or any other evidence of other than minor instability occurs which is attributable to design of the relocated stream or work conducted by the permittee or the permittee's contractor(s), the permittee, upon discovery of the instability, shall contact the USACE and recommend corrective action; this corrective action must be approved by the USACE prior to implementation by the permittee.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Total number of reference photo locations at this site:

4 photos were taken from 2 photo point locations and 2 overview photos

Dates reference photos have been taken at this site: 11/8/12, 8/21/13, 6/17/14, 7/8/15

Individual from whom additional photos can be obtained (name, address, phone):						
Other Information relative to site photo reference: A site map with photo point locations is include with this report.						
If required to complete Level 3 monitoring <u>only</u> stop here; otherwise, complete section 2.						
Section 2. PLANT SURVIVAL Attach plan sheet indicating reference photos.						
Identify specific problem areas (missing, stressed, damaged or dead plantings): Small sprigs of Japanese knotweed were noted onsite.						
Estimated causes, and proposed/required remedial action: The small sprigs of Japanese Knotwee were sprayed with an herbicide application on 8/21/13, 5/8/14, 7/23/14, and 7/8/15.						
ADDITIONAL COMMENTS: <u>Live stakes were planted along the streambank on 11/26/12. Blac willow, silky dogwood, and tag alder were noted surviving along the streambank.</u>						
If required to complete Level 1 and Level 2 monitoring <u>only</u> stop here; otherwise, complet section 3.						

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. <u>Physical measurements of channel stability/morphology will not be required.</u> Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The Crooked Creek stream relocation is stable for the Year 4 evaluation. The right bank of Middle Fork Creek at the confluence of Crooked Creek and Middle Fork Creek is also stable for the Year 4 evaluation. NCDOT will continue to monitor the channel stability at the Crooked Creek and Middle Fork Creek sites.

Date	Station Number	Station Number	Station Number	Station Number	Station Number
Structure					
Туре					
Is water					
piping					
through or					
around					
structure?					
Head cut or					
down cut					
present?					
Bank or scour					
erosion					
present?					
Other					
problems					
noted?					
Bankfull					
event dates					
and how it					
was noted					

Section 4. DEBIT LEDGER

The entire Crooked Creek and Middle Fork Creek stream relocation sites were used for the B-4183 project to compensate for unavoidable stream impacts.

Crooked Creek



Photo Point #1 (Upstream)



Photo Point #2 (Upstream)



Overview Photo Looking Downstream of Crooked Creek from Crooked Creek Rd



Photo Point #1 (Downstream)




Photo Point #2 (Downstream)

Middle Fork Creek




Overview Photo Looking Downstream of Middle Fork Creek from Crooked Creek Rd

Year 4 – July 2015



Site Map B-4183 Crooked Creek and Middle Fork Creek Site Photo Point Locations Madison County, North Carolina

325 SQUARE METERS LIVE STAKING



SEE EC-8 AND PROJECT SPECIAL PROVISIONS

Site Map B-4183 Crooked Creek and Middle Fork Creek Site Live Staking Area Madison County, North Carolina

